

Vater Resources Program

FORM 1 – Measuring Device Information

Please fill out one form for each measuring device.

WATER RIGHT HOLDER(S): WATER RIGHT DOCUMENT NO(S):		
Name(s)	Certificate, Permit, Claim, or Court Claim	
ser's name for diversion/withdrawal point:	(ex. Well #1, Blue well house) ABH3	
ease include an up-close photo of the face of th	he meter.	
ow Type: Open Channel Flow Rressur	rized Pipe Flow	
easure more than one source? Yes X eat share a common measuring device (ex. two	No If yes, please provide a list of all the sources wells or two pumped diversions):	
eter Type (ex. magnetic, propeller, flume, etc.)	PROPELLER	
and: BADGER	Model No.:	
rial No.: 94191747	Units of Measure (gal, cfs, or ac-ft): GAL	
evice Roll-Over No.: 99,999,999	Device Multiplier (ex. X100, X0.01): 100	
ate Installed/Calibrated: 1994	Fish screen for surface water diversion? Yes No	
OCATION OF THE MEASURING DEVICE:		
ection: 36 Township: 19 Ran	nge: 1W (1/4):(1/4/4):	
atitude (optional): 47°05.31N (AD 83 Datum in Decimal Degrees preferred)	Longitude (optional):	
meter within 100 feet of the point of diversion	or withdrawal? X Yes No	
OMMENTS:		
I hereby certify that all information repo	orted on this form is correct to the best of my knowledge.	
Printed Name: RICK HANCOCK	Phone No.: (360) 459 0513	
	VE NE City: LACEY State: WA	
E-mail: RICKHEHAWKS PRAI		
0.11	Date: 12/10/2010	
- participation		



ater Resources Program

FORM 1 – Measuring Device Information Please fill out one form for each measuring device.

WATER RIGHT HOLDER(S): WATER RIGHT DOCUMENT NO(S):		
Name(s)	Certificate, Permit, Claim, or Court Claim	
ser's name for diversion/withdrawal point: BOUT THE MEASURING DEVICE: lease include an up-close photo of the face of the	WELL # Z WODLANDS ABH (ex. Well #1, Blue well house) the meter.	
low Type: Open Channel Flow Pressur	rized Pipe Flow	
leasure more than one source? Yes X at share a common measuring device (ex. two	No If yes, please provide a list of all the sources wells or two pumped diversions):	
leter Type (ex. magnetic, propeller, flume, etc.)	: PROPELLER	
rand: BADGER	Model No.:	
erial No.: 9419174 6	Units of Measure (gal, cfs, or ac-ft): GAL	
evice Roll-Over No.: 99,999,999	Device Multiplier (ex. X100, X0.01): 100	
ate Installed/Calibrated: 1994	Fish screen for surface water diversion? Yes X No	
OCATION OF THE MEASURING DEVICE:		
ection: 36 Township: 19 Rai	nge:/W (½): (½½½):	
atitude (optional): 47° 05 242 N NAD 83 Datum in Decimal Degrees preferred)	Longitude (optional):	
meter within 100 feet of the point of diversion	or withdrawal? X Yes No	
OMMENTS:		
I hereby certify that all information repo	orted on this form is correct to the best of my knowledge.	
Printed Name: RICK HANCOCK	Phone No.: (3/4/59- 05/3	
	ANE NE City: LACEY State: WA	
E-mail: RICKH@HAWKSPR		
Signature: Bick Hamcoc		

Woodlands

ABH-211

SWLs (bt.c) ABH-327

Meter (Gallons)	Pump On/Off	Date	Level (feet)	Meter (Gallons)	Pump On/Off
		5/4/12	218.0		90 - STORY - STORY
80,945,400	Off	5/11/12	217.8	94,161,900	Off
81,450,600	Off	5/18/12	219.0	94,574,400	Off
81,858,300	Off	5/25/12	217.5	94,574,400	Off
82,412,900	On	6/1/12	220.1	95,116,700	Off
82,416,900	Off	6/8/12	217.5	95,116,700	Off
82,416,900	Off	6/15/12	217.7	95,116,700	Off
82,923,000	Off	6/22/12	219.0	95,521,900	Off
83,057,300	Off	6/29/12	218.5	95,617,900	Off
83,310,600	On	7/6/12	244.0 pumpi	95,789,100	On
84,531,300	Off	7/13/12	222.6	96,762,500	Off
85,243,100	Off	7/20/12	224.9	97,204,100	Off
85,947,800	On	7/27/12	245.0 mm	j. 4 97,762,500	On
86,890,800	Off	8/3/12	219.5	98,512,000	Off
88,122,700	Off	8/10/12	220.5	99,488,700	Off
89,271,200	On	8/17/12	244.5 pumpi	100,383,500	On
90,188,500	Off	8/24/12	223.0	101,093,800	Off
		8/31/12			
		9/7/12			12 - 40 T 340 T 1
		9/14/12			
		9/21/12		and the Beautiful Course of the Beautiful Course to the Course of the Co	
		9/28/12			
		10/5/12			
		10/12/12			
		10/19/12			
		10/26/12			
		11/2/12			
		11/9/12			
		11/16/12			
		11/23/12			

(casing height is 3,2 feet)


swl data consistent with previous years

	11/30/12		
	12/7/12		
	12/14/12		
	12/21/12		
	12/28/12		
9,243,100		6,931,900	

epths Links (BBP-643) Woods (ABH-327) 8/10 8/17 8/24 8/31 9/21 9/28 10/5 10/12 10/19 9/7 9/14 10/26

Woodlands Irrigation Usage in Gallons G2-28489

Month	2007	2008	2009	2010	2011
January	0	0	0	0	0
February	0	0	0	142,000	0
March	0	0	0	0	0
April	0	51,000	720,000	7,000	25,000
May	3,330,000	2,683,000	2,168,000	37,000	21,000
June	7,085,000	5,256,000	8,116,000	620,000	3,707,000
July	7,772,000	10,611,000	11,889,000	7,385,000	5,575,000
August	6,167,000	4,252,000	6,363,000	6,989,000	6,099,000
September	2,117,000	4,952,000	4,111,000	2,260,000	2,840,000
October	82,000	104,000	536,000	55,000	35,000
November	0	54,000	0	0	0
December	0	0	0	0	0
Totals	26,553,000	27,963,000	33,903,000	17,495,000	18,302,000
	81.5 AF	85.8 AF	104.0 AF	53.7 AF	56.2 AF



"swl" Valleys are not state levels

- well was pumping

- data compared with previous years

swls are consistent appear to be stable

mp

Swahn

www.adolfson.com

ESA Adolfson

5309 Shilshole Avenue NW Suite 200 Seattle, WA 98107 206.789.9658 phone 206.789.9684 fax

RECEIVED

OCT 222009

DEPARTMENT OF ECOLOGY

October 15, 2009

Mr. Glenn Hirai Oki Golf 1416 – 112th Avenue NE Bellevue, WA 98004

RE: Hawks Prairie Golf Course Monitoring Results - Woodlands Course

Dear Glenn:

As requested, ESA Adolfson (Adolfson) has continued to conduct monthly ground water level monitoring throughout 2009, as well as chloride monitoring during the months of April and August from the two wells located at the Woodlands Course of the Golf Club at Hawks Prairie in Lacey, Washington.

Per our agreement, we began collecting monthly water levels in August 2007. In a letter dated October 13, 2008, we reported on monthly water levels recorded and chloride sample results through September 2008.

We have continued to collect monthly water levels throughout the remainder of 2008 and through September 2009. Water levels were collected using an electronic water level indicator, measured to the nearest 0.1 foot. Water levels are presented both as the raw number measured in the field at the top of the well casing, and the calculation of the depth below ground surface. In the case of well ABH 211, the top of the well casing is located 3.2 feet above grade. In the case of ABH 327, the top of the well casing is located 2.5 feet above grade.

Also per our agreement, we attempted collection of chloride samples from the wells in April and August of this year. We collected samples in April, however were unable to collect samples in August due to an issue with starting the well pumps at that time. We did, however, collect chloride samples for both Woodlands Course wells in September of this year. The chloride samples were collected in the field and analyzed by Aquatic Research in Seattle. Copies of the laboratory results are attached for your reference.

The attached tables provide a summary of the water levels and chloride monitoring results collected for each well for the 2009 monitoring season. The results are well below the action level of 100 mg/L for chloride, and are consistent with the data collected in 2007 and 2008. Per your permit requirements, a copy of these results should be submitted to the Washington State Department of Ecology by October 15th of this year.

ESA Adolfson

Page 2

Please don't hesitate to call if you have any questions or require additional information. We are scheduled to continue monitoring water levels on a monthly basis, and collect chloride samples from these two wells in April and August of 2010.

Very truly yours,

Lisa Adolfson

Senior Project Manager

ESA Adolfson

Attachments: Summary tables

Laboratory data



Hawks Prairie Golf Course
Hawks Prairie Course Well Number ABH 211

	Date	Water Level Measurement*	Calculated depth below ground surface (-3.2 feet)	Pump Status	Chloride concentration (mg/L)
4	10/31/2008	225.5	222.3	not running	
1/2	11/19/2008	256.0	252.8	running	
whing _	12/11/2008	223.4	220.2	not running	
,	1/21/2009	224.7	221.5	not running	AN THE TIME WAS ALLE STOR THE PROPERTY AND THE WAS ALLE WAS ALLE WAS ALLE THE TIME THE TIME THE WAS ALLE
	2/23/2009	224.5	221.3	not running	
	3/12/2009	225.0	221.8	not running	
	4/14/2009	224.6	221.4	not running	15.7
	5/13/2009	224.5	221.3	not running	***************************************
	6/11/2009	225.0	221.8	not running	
mpirt =	7/22/2009	253.4	250.2	running	
18	8/13/2009	226.7	223.5	not running	
	9/30/2009	225.8	222.6	not running	8.41

^{*}Water levels are measured from the top of the above ground well casing. This location is 3.2 feet above ground surface.



Well \$1

Hawks Prairie Golf Course Hawks Prairie Course Well Number ABH 327

		HIGHING I LUMING	oodisc vicii idali	INCI / INCII OMI	
	Date	%t→c Water Level Measurement*	Calculated depth below ground surface (-2.5 feet)	Pump Status	Chloride concentration (mg/L)
1 12 11	10/31/2008	222.9	220.4	not running	
umpings	11/19/2008	245.6	243.1	running	AND AND THE THE THE THE SEE AS AS SECTION TO THE THE SEA THE VEH AS THE SET AS AND THE SET AND THE SET AS A SE
1 8	12/11/2008	223.4	220.9	not running	
	1/21/2009	222.5	220.0	not running	ANAMENT OF THE STATE OF THE STA
	2/23/2009	222.3	219.8	not running	AAA COO COO COO COO COO COO COO COO COO
	3/12/2009	222.9	220.4	not running	# 1
	4/14/2009	222.4	219.9	not running	5.96
	5/13/2009	222.0	219.5	not running	
	6/11/2009	222.6	220.1	not running	
smping >	7/22/2009	249.5	247.0	running	NAME OF THE PARTY
	8/13/2009	224.6	222.1	not running	7-4-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-
	9/30/2009	223.8	221.3	not running	8.41

^{*}Water levels are measured from the top of the above ground well casing. This location is 2.5 feet above ground surface.





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103 PHONE: (206) 632-2715 FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-65

PAGE 1

REPORT DATE:

04/28/09

DATE SAMPLED:

04/14/09

DATE RECEIVED:

04/15/09

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

CASE NARRATIVE

Three water samples were delivered to the laboratory in good condition. The samples were analyzed according to the chain of custody. No difficulties were encountered in the preparation or analysis of these samples. Sample data follows while QA/QC data is contained on subsequent pages.

SAMPLE DATA

	CHLORIDE
SAMPLE ID	(mg/l)
LINKS WELL	1.76
327 WELL	5.96
211 WELL	15.7





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103 PHONE: (206) 632-2715 FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-65

PAGE 2

REPORT DATE: DATE SAMPLED: 04/28/09

04/14/09

DATE RECEIVED:

04/15/09

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

QA/QC DATA

	the state of the s
QC PARAMETER	CHLORIDE
	(mg/l)
METHOD	SM18 4500CLC
DATE ANALYZED	04/28/09
DETECTION LIMIT	0.50
DUPLICATE	
SAMPLE ID	BATCH
ORIGINAL	8.41
DUPLICATE	8.31
~	
RPD	1.17%
SPIKE SAMPLE	
SAMPLE ID	BATCH
ORIGINAL	8.41
SPIKED SAMPLE	18,4
SPIKE ADDED	10.0
% RECOVERY	99.71%
QC CHECK	
FOUND	28.9
TRUE	30.0
% RECOVERY	96.45%
BLANK	< 0.50
	-5100

RPD = RELATIVE PERCENT DIFFERENCE.

NA = NOT APPLICABLE OR NOT AVAILABLE.

NC = NOT CALCULABLE DUE TO ONE OR MORE VALUES BEING BELOW THE DETECTION LIMIT.

OR = RECOVERY NOT CALCULABLE DUE TO SPIKE SAMPLE OUT OF RANGE OR SPIKE TO LOW RELATIVE TO SAMPLE CONCENTRATION.

SUBMITTED BY:

Laboratory Director





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103

PHONE: (206) 632-2715 FAX:

FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-67

PAGE 1

REPORT DATE:

10/07/09

DATE SAMPLED:

09/30/09

DATE RECEIVED:

10/05/09

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

CASE NARRATIVE

Two water samples were delivered to the laboratory in good condition. The samples were analyzed according to the chain of custody. No difficulties were encountered in the preparation or analysis of these samples. Sample data follows while QA/QC data is contained on subsequent pages.

SAMPLE DATA

	CHLORIDE
SAMPLE ID	(mg/l)
WELL 327	8.41
WELL 211	8.41





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103

PHONE: (206) 632-2715

FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-67

PAGE 2

REPORT DATE:

10/07/09

DATE SAMPLED:

09/30/09

DATE RECEIVED:

10/05/09

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

QA/QC DATA

QC PARAMETER	CHLORIDE
	(mg/l)
METHOD	SM18 4500CLC
DATE ANALYZED	10/05/09
DETECTION LIMIT	0.50
DUPLICATE	
SAMPLE ID	ВАТСН
ORIGINAL	5.47
DUPLICATE	5.18
RPD	5.50%
SPIKE SAMPLE	
SAMPLE ID	ВАТСН
ORIGINAL	5.47
SPIKED SAMPLE	14.8
SPIKE ADDED	10.0
% RECOVERY	92.87%
QC CHECK	
FOUND	28.4
TRUE	30.0
% RECOVERY	94.82%
BLANK	<0.50

RPD = RELATIVE PERCENT DIFFERENCE

NA = NOT APPLICABLE OR NOT AVAILABLE.

NC = NOT CALCULABLE DUE TO ONE OR MORE VALUES BEING BELOW THE DETECTION LIMIT

OR = RECOVERY NOT CALCULABLE DUE TO SPIKE SAMPLE OUT OF RANGE OR SPIKE TO LOW RELATIVE TO SAMPLE CONCENTRATION.

SUBMITTED BY:

Steven Lazoff Laboratory Director



Hawks Prairie Golf Course
Hawks Prairie Course Well Number ABH 211

Date	Water Level Measurement*	Calculated depth below ground surface (-3.2 feet)	Pump Status	Chloride concentration (mg/L)
1/29/2008	222.2	219	not running	
2/27/2008	221.1	217.9	not running	
3/25/2008	221.9	218.7	not running	
4/24/2008	253.9	250.7	running	9.68
5/22/2008	222.3	219.1	not running	
6/19/2008	224.8	221.6	not running	
7/31/2008	224.6	221.4	not running	
8/29/2008	225.3	222.1	not running	21
9/30/2008	225.4	222.2	not running	

^{*}Water levels are measured from the top of the above ground well casing. This location is 3.2 feet



Hawks Prairie Golf Course Hawks Prairie Course Well Number ABH 327

Date	Water Level Measurement*	Calculated depth below ground surface (-3.2 feet)	Pump Status	Chloride concentration (mg/L)
1/29/2008	220.2	217.7	not running	
2/27/2008	220	217.5	not running	46.4444.0000000000000000000000000000000
3/25/2008	220	217.5	not running	
4/24/2008	242.4	239.9	running	3.81
5/22/2008	220.2	217.7	not running	
6/19/2008	222.7	220.2	not running	
7/31/2008	222.3	219.8	not running	
8/29/2008	223.2	220.7	not running	17.8
9/30/2008	223.3	220.8	not running	

^{*}Water levels are measured from the top of the above ground well casing. This location is 2.5 feet above ground surface.





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103 PHONE: (206) 632-2715 FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-60

PAGE 1

REPORT DATE:

05/08/08

DATE SAMPLED: 04/24/08 DATE RECEIVED:

04/24/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

CASE NARRATIVE

Two water samples were delivered to the laboratory in good condition. The samples were analyzed according to the chain of custody. No difficulties were encountered in the preparation or analysis of these samples. Sample data follows while QA/QC data is contained on subsequent pages.

SAMPLE DATA

	CHLORIDE		
SAMPLE ID	(mg/l)		
WELL ABH 211	9.68		
WELL ABH 327	3.81		





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103

PHONE: (206) 632-2715

FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-60

PAGE 2

REPORT DATE:

05/08/08

DATE SAMPLED: 04/24/08

DATE RECEIVED:

04/24/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

QA/QC DATA

QC PARAMETER	CHLORIDE
	(mg/l)
METHOD	SM18 4500CLC
DATE ANALYZED	05/08/08
DETECTION LIMIT	0.50
DUPLICATE	
SAMPLE ID	BATCH
ORIGINAL	42.3
DUPLICATE	42.7
RPD	0.92%
SPIKE SAMPLE	
SAMPLE ID	BATCH
ORIGINAL	42.3
SPIKED SAMPLE	52.2
SPIKE ADDED	10.0
% RECOVERY	98.73%
QC CHECK	
FOUND	28.3
TRUE	30.0
% RECOVERY	94.17%
BLANK	< 0.50
DEATITIE	10.50

RPD = RELATIVE PERCENT DIFFERENCE.

NA = NOT APPLICABLE OR NOT AVAILABLE.

NC = NOT CALCULABLE DUE TO ONE OR MORE VALUES BEING BELOW THE DETECTION LIMIT.
OR = RECOVERY NOT CALCULABLE DUE TO SPIKE SAMPLE OUT OF RANGE OR SPIKE TO LOW RELATIVE TO SAMPLE CONCENTRATION

3MITTED BY:

Laboratory Director

9



Aquatic Research Incorporate

3927 Aurora Ave. N / Seattle, WA 98103 / (206) 632-2715

AIN-OF-CUSTODY RECORD ONT: 4 A Addition	SHEET OF PROJECTIO: Haules Prairie						
SAMPLING DATE: 4/24/00 SAMPLERS: 4/200 (300)			CASE FILE NO.: DATA RECORDED BY:				
SAMPLE INFORMATION							
	PARA	AMETERS					
				B O			
SAMPLE DATE/TIME COLLECTED				T T # NOTES			
Well ABH ZII 4/24 Z:10pm							
Upll ABH 3274/24 2.2300							
)			
Printed Name AATON BOWY	Date/Time	Received By	500	Date/Time, 4/04			
Signature		Sin		1630			
Affiliation IECA ASSITSON		7476		<u> </u>			
Relinquished By Printed Name	Date/Time	Received By		Date/Time			
ature							
Miscellaneous Notes (Hazardous Materials, Quick turn-arou	nd time, etc.):						



LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103

PHONE: (206) 632-2715

FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-62

PAGE 1

REPORT DATE:
DATE SAMPLED:

09/13/08

08/28/08

DATE RECEIVED:

08/29/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

CASE NARRATIVE

Three water samples were delivered to the laboratory in good condition. The samples were analyzed according to the chain of custody. No difficulties were encountered in the preparation or analysis of these samples. Sample data follows while QA/QC data is contained on subsequent pages.

SAMPLE DATA

	CHLORIDE
SAMPLE ID	(mg/l)
ABH 211	21.0
ABH 327	17.8
LINKS COURSE	1.86





LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103

PHONE: (206) 632-2715

FAX: (206) 632-2417

CASE FILE NUMBER:

ADL001-62

PAGE 2

REPORT DATE:

09/13/08

DATE SAMPLED:

08/28/08

DATE RECEIVED:

08/29/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM ADOLFSEN ASSOCIATES

QA/QC DATA

QC PARAMETER	CHLORIDE
	(mg/l)
METHOD	SM18 4500CLC
DATE ANALYZED	09/12/08
DETECTION LIMIT	0.50
DUPLICATE	
DOI BICHTE	
SAMPLE ID	BATCH
ORIGINAL	6.55
DUPLICATE	6.35
RPD	3.03%
KFD	3.03 //
SPIKE SAMPLE	
SPIKE SAMPLE	
CAMPIETO	D.I. MOVI
SAMPLE ID	BATCH
ORIGINAL	6.55
SPIKED SAMPLE	16.2
SPIKE ADDED	10.0
% RECOVERY	96.78%
QC CHECK	
FOUND	28.4
TRUE	30.0
% RECOVERY	94.82%
BLANK	< 0.50

NA = NOT APPLICABLE OR NOT AVAILABLE.

NC = NOT CALCULABLE DUE TO ONE OR MORE VALUES BEING BELOW THE DETECTION LIMIT.

OR = RECOVERY NOT CALCULABLE DUE TO SPIKE SAMPLE OUT OF RANGE OR SPIKE TO LOW RELATIVE TO SAMPLE CONCENTRATION.

Laboratory Director



Aquatic Research Incorporated 5927 Aurora Ave. N / Seattle, WA 98103 / (206) 632-2715

1406001-67.

CF1-0	F-CUSTODY ESA A	RECORD							SHE	-		II s	OF
				,						JECT ID			
AMPLING AMPLERS	//	8/29/2	COST	>	+0	7	- i -	1		E FILE N			
AMPLENS	Agar	1 Goo	7	Dean	+ 0	100	ste	do	- DAT	A RECC	IKDE	D BA:	7
AMPLE IN	FORMATION				,								
					Р	ARA	AMETE	RS					
			TIII		TT	T	П		TIT		Ť	7	
			0									В	
			7:1									0	
			ò			-						T	
SAMPI		DATE/TIME	3									T.	
. ID		COLLECTED	14			1						#	NOTES
ABL	1 711	8/28 10:55m	X										
121	1 777	101	1//	\top	++	+-					+	++-	manuf
1101	1 2CF	828 1100an	X		11	+							
Links	course	428 0:40m	M										A.
	The state of the s					T							
		-	+++		++	+						-	
									1 2				
			+++	+++		+-	-			5	-	H	
						1							
(1	
<u> </u>			+++	++	++	+					+		
	**		+++	\dashv	44	4							
	2.54			\top	1.								
			+++	-	++	+	 .		\vdash	HH	+	$\vdash\vdash$	
	,	 	+++	++	++	+		H		+++			* * * * * * * * * * * * * * * * * * * *
	·····	l. —	+++	++	++	+					-	-	
	*												***
1													
,	•		+++	++		+	-	-	++-		+		
					$\perp \perp$								
		- h											,
										L			
	Relinquished By	17	Date/Tim	e,	/		Receive	d By			Da	te/Time)
nted Name	AAZON	Gazy	121	29/	28		5%	NETS	00			8/2	5/08
nature	1	7/	91	1			5	7					094
liation	ESA A	dolEson	1 6-	15	3-		6	AVEC	6.			18	
											,		
	Relinquished By		Date/Tim	e		•	Receive	ed By	1. 3.		Da	te/Time	
i(ame			-								-	-	
gnature			1				- 4				-		
filiation	<u> </u>												
													A.
scellaneous l	Notes (Hazardous M	aterials, Quick turn-arou	nd time, et	c.):									
													- Parketon



Recordall® Cold Water Top Load Bronze Disc Meter Size 2" (DN 50mm) NSF/ANSI Standard 61 Certified, Annex G

DESCRIPTION

Badger Meter offers the Recordall Disc meter in Cast Bronze and a Lead-Free Alloy. The Lead-Free Alloy (Trade designation: M170-LL) version has been certified to comply with NSF/ANSI Standard 61, Annex G and carries the NSF-61 Mark on the housing. All components of the Lead-Free Alloy meter, i.e., disc, chamber, housing, seals, etc. comprise the certified system.

APPLICATIONS: For use in measurement of potable cold water in residential, commercial and industrial services where flow is in one direction only.

OPERATION: Water flows through the meter's strainer and into the measuring chamber where it causes the disc to nutate. The disc, which moves freely, nutates on its own ball, guided by a thrust roller. A drive magnet transmits the motion of the disc to a follower magnet located within the permanently-sealed register. The follower magnet is connected to the register gear train. The gear train reduces the disc nutations into volume totalization units displayed on the register dial face.

OPERATING PERFORMANCE: The Badger Meter Recordall Disc meters meet or exceed registration accuracy for the low flow rates (95%), normal operating flow rates (100 \pm 1.5%), and maximum continuous operation flow rates as specifically stated by AWWA Standard C700.

CONSTRUCTION: Badger Meter Recordall Disc meter construction, which complies with ANSI/AWWA standard C700, consists of three basic components: bronze meter housing, measuring chamber, and permanently, sealed register. A corrosion-resistant engineered polymer material is used for the measuring chamber.

To simplify maintenance, the register, measuring chamber, and strainer can be replaced without removing the meter housing from the installation. No change gears are required for accuracy calibration. Interchangeability of parts among like-sized meters also minimizes spare parts inventory investment. The built-in strainer has an effective straining area of twice the inlet size.


MAGNETIC DRIVE: Direct magnetic drive, through the use of high-strength magnets, provides positive, reliable and dependable register coupling for straight-reading, remote or automatic meter reading options.

SEALED REGISTER: The standard register consists of a straight-reading, odometer-type totalization display, 360° test circle with center sweep hand and flow finder to detect leaks. Register gearing consists of self-lubricating engineered polymer gears to minimize friction and provides long life. Permanently sealed; dirt, moisture, tampering and lens fogging problems are eliminated. Multi-position register simplifies meter installation and reading. Automatic meter reading systems are available for all Recordall Disc meters. All reading options are removable from the meter without disrupting water service.

TAMPER-PROOF FEATURES: Customer removal of the register to obtain free water can be prevented when the optional tamper detection seal wire screw/or Torx* tamper seal resistant screw is added to the meter. Both can be installed at the meter site or at the factory.

MAINTENANCE: Badger Meter Recordall Disc meters are designed and manufactured to provide long-term service with minimal maintenance. When maintenance is required, it can be performed easily either at the meter installation or at any other convenient location. As an alternative to repair by the utility, Badger Meter offers various maintenance and meter component exchange programs to fit the needs of the utility.

CONNECTIONS: Tailpieces/Flanges for installations of meters on various pipe types and sizes, including misaligned pipes, are available as an option.



Model 170 shown with optional 1" Test Plug

SPECIFICATIONS

Typical Operating 2 1/2 - 170 GPM (.57 to 39 m³/hr)
Range (100% ± 1.5%)

Low Flow 1 1/2 GPM (.34 m³/hr) (Min. 95%)

Maximum 100 GPM (23 m³/hr)

Continuous Operation
Pressure Loss 3.3 PSI at 100 GPM
at Maximum (.23 bar at 23 m³/hr)

Continuous Operation (.23 Bar

Maximum Operating 80°F (26°C)
Temperature

Maximum Operating 150 PSI (10 bar)
Pressure

Measuring Element Nutating disc, positive displacement

Register Type Straight reading, permanently

sealed magnetic drive standard. Remote reading or Automatic Meter Reading units optional.

Registration 100 Gallons, 10 Cubic Feet, 1 m³
Register Capacity 100,000,000 Gallons,

10,000,000 Cubic Feet, 1,000,000 m³.

Meter Connections 2" AWWA two bolt elliptical flange, drilled, or 2" - 11 1/2 NPT internal pipe threads.

Optional Test Plug 1" NPT test plug (TP) available on elliptical long and short versions.

MATERIALS

Meter Housing Cast Bronze, Lead-Free Alloy

Housing Top Plates Bronze, Lead-Free Alloy

Measuring Chamber Engineered Polymer

Disc Engineered Polymer
Trim Stainless Steel/Bronze
Strainer Engineered Polymer
Disc Spindle Stainless Steel
Magnet Ceramic


Magnet Spindle Stainless Steel


Register Lid and Box Engineered Polymer or Bronze
Generator Housing Engineered Polymer

Technical Brief

PRESSURE LOSS CHART

ACCURACY CHART





METER SIZE	METER MODEL	A LAYING LENGTH	B HEIGHT REG./RTR	C HEIGHT GEN.	D CENTERLINE BASE	WIDTH	APPROX. SHIPPING WEIGHT
2"	170 EL, Hex.	15 ¹ / ₄ "	8"	9³/ ₈ "	2 ⁷ / ₈ "	9 ¹ / ₂ "	30 lb.
(50mm)	170 EL, TP	(387mm)	(203mm)	(238mm)	(73mm)	(241mm)	(13.6kg)
2"	170 ELL,	17"	8"	9 ³ / ₈ "	2 ⁷ / ₈ "	9 ¹ / ₂ "	30 lb.
(50mm)	170 ELL, TP	(432mm)	(203mm)	(238mm)	(73mm)	(241mm)	(13.6kg)

EL = Elliptical

ELL = Elliptical Long

Hex = Hexagon, $2'' - 11^{1}/_{2}$ NPT Thread

TP=Test Plug 1"


Sweep Hand Registration

MODEL	GALLON	CU.FT.	CU. METER	
M170	100	10	1	-









RTR and Recordall are registered trademarks of Badger Meter, Inc.

Other trademarks appearing in this document are the property of their respective entities.

Copyright 2011 Badger Meter, Inc. All rights reserved.



Due to continuous research, product improvements and enhancements, Badger Meter reserves the right to change product or system specifications without notice, except to the extent an outstanding contractual obligation exists.

Badger Meter | P.O. Box 245036, Milwaukee, Wisconsin 53224-9536 800-876-3837 | infocentral@badgermeter.com | www.badgermeter.com

